

**Handheld Aluminium Alloy Paint
Curing Equipment**

Instruction Manual

Model No: FY-1000WS



Handheld Aluminium Alloy Paint Curing Equipment

INSTRUCTION MANUAL

*Please read this manual carefully before installing or servicing this equipment.

Precaution



1. This equipment is designed for paint curing application. Keep a safe distance between emitter and panel. Improper servicing can cause paint surface damage.
2. Installation and service must be performed by a qualified installer or service agent.
3. The system has been designed for easy installation, low operating costs and minimal maintenance. The warranty does not cover lamp tube defects resulting from misuse or improper operation.
4. Disconnect power source when the equipment is not in use for a long period.
5. The lamp tube should not be perpendicular to the ground when the equipment is operating. Otherwise, it will shorten the life of the lamp tube.
6. Turn off the equipment after using. Place the equipment in a safe place to avoid damage to the lamp tube.

Technical Parameter


Model	FY-1000WS
Parameter	
Power Supply	220V/±10V 50/60Hz Single Phase
Input Power	1100W
Curing Area	800×450mm
Temperature	100°C
Timer	0min -60 min Adjustable
Light intensity	100%

Installation

With flexible locking system, the cassette can be moved up and down easily



Controls



Operation

1. Set curing time according to the requirement of paint for curing.
2. To achieve the best effect, the emitters should be parallel with the paint surface. Keep distance of 30-60 cm away from the panel.
3. During the process of curing, the paint surface must be clean without water and impurities.
4. Switch on the power supply and set up the curing time to start curing process.
5. Turn off the equipment after using. Place the equipment in a safe place to avoid damage to the lamp.